


Rot Repair:

Wood Door and Panel




Three panel wood door, two panels with extensive rot.



Naturally, the rot went deeper than it first appeared.



Replace bottom of fixed door panel.
Replace rotten plywood subfloor.
Replace bottom 12" of center post.



Quote for new three panel wood door, installed:

\$3,100.00



Our Rot Repair:

\$1,800.00